

HOME RESOURCE SOLUTIONS

(253) 271-0402 contact@hrsinspects.com https://hrsinspects.com



RESIDENTIAL REPORT

123 Sample Street Sample Report WA 98765

> TEST TEST MAY 2, 2021



Inspector

Daniel Arnett
Certified Master Inspector, IAC2, Sewer Scope
Certified, Radon measurement technician, IR
Certified
2532710402
hrsinspects@gmail.com

TABLE OF CONTENTS

1: Inspection Details	6
2: Exterior	7
3: Roof	12
4: Garage	14
5: Doors, Windows & Interior	16
6: Plumbing	19
7: Electrical	21
8: Attic, Insulation & Ventilation	22
9: Fireplace	23
10: Heating	24
11: Cooling	25
12: Basement, Foundation, Crawlspace & Structure	26

Home Resource Solutions Page 2 of 27

What Really Matters in a Home Inspection





Watch later



Page 3 of 27 Home Resource Solutions

SUMMARY

- 2.1.1 Exterior Siding, Flashing & Trim: Cracking Minor
- 2.1.2 Exterior Siding, Flashing & Trim: Paint overspray
- 2.2.1 Exterior Exterior Doors: Hardware Damaged
- 2.3.1 Exterior Walkways, Patios & Driveways: Driveway Cracking Minor
- 2.4.1 Exterior Decks, Balconies, Porches & Steps: Deck Water Sealant Required
- 2.4.2 Exterior Decks, Balconies, Porches & Steps: Improper Deck Construction Practices
- 2.5.1 Exterior Eaves, Soffits & Fascia: Paint/Finish Failing
- 2.5.2 Exterior Eaves, Soffits & Fascia: Wasps Nest
- 3.1.1 Roof Coverings: Moss buildup
- 3.2.1 Roof Roof Drainage Systems: Debris
- 3.2.2 Roof Roof Drainage Systems: Gutter Improperly Sloped
- 3.2.3 Roof Roof Drainage Systems: Gutter Leakage
- 3.4.1 Roof Skylights, Chimneys & Other Roof Penetrations: Wood rot around chimney chase
- 4.1.1 Garage Ceiling: Damaged
- 4.2.1 Garage Floor: Staining
- 4.3.1 Garage Walls & Firewalls: Damaged Drywall
- 4.4.1 Garage Garage Door: Panel Damage
- 5.1.1 Doors, Windows & Interior Doors: Screendoor torn
- 5.3.1 Doors, Windows & Interior Floors: Carpet Stains
- 5.3.2 Doors, Windows & Interior Floors: Tiles Loose
- 5.4.1 Doors, Windows & Interior Walls: Nail Pops
- 5.4.2 Doors, Windows & Interior Walls: Paint Cracking
- 5.4.3 Doors, Windows & Interior Walls: Poor Patching
- 5.5.1 Doors, Windows & Interior Ceilings: Possible Mold
- 5.5.2 Doors, Windows & Interior Ceilings: Sagging Drywall
- 5.6.1 Doors, Windows & Interior Steps, Stairways & Railings: Baluster Spaces Too Wide
- 6.2.1 Plumbing Drain, Waste, & Vent Systems: Improper Connection
- 6.2.2 Plumbing Drain, Waste, & Vent Systems: Leaking Pipe
- 6.3.1 Plumbing Water Supply, Distribution Systems & Fixtures: Distribution Pipe Leaking
- 7.6.1 Electrical Smoke Detectors: Low Battery
- 8.1.1 Attic, Insulation & Ventilation Attic Insulation: Some insulation is compressed
- 9.1.1 Fireplace Vents, Flues & Chimneys: Chimney Liner Dirty
- 10.1.1 Heating Equipment: Filter Dirty
- 10.3.1 Heating Distribution Systems: Duct Damaged
- 12.1.1 Basement, Foundation, Crawlspace & Structure Foundation: Foundation Cracks Minor
- 12.2.1 Basement, Foundation, Crawlspace & Structure Basements & Crawlspaces: Efflorescence
- 12.2.2 Basement, Foundation, Crawlspace & Structure Basements & Crawlspaces: High Moisture Levels
- 12.3.1 Basement, Foundation, Crawlspace & Structure Floor Structure: Evidence of Water Intrusion

Home Resource Solutions Page 4 of 27

○ 12.4.1 Basement, Foundation, Crawlspace & Structure - Wall Structure: Cracks - Minor

Home Resource Solutions Page 5 of 27

1: INSPECTION DETAILS

Information

In Attendance

Client, Home Owner

Temperature (approximate)

55

In Attendance

Client

Style

Rambler

Type of Building

Single Family

Occupancy

Furnished, Occupied

Occupancy

Furnished, Occupied

Weather Conditions

Clear

Style

Rambler



Temperature (approximate)

55 70 Fahrenheit (F)

Type of Building

Single Family, Attached

Weather Conditions

Clear

Limitations

General

INSPECTION IS LIMTED TO A VISUAL INSPECTION

Inspection is limited to a visual inspection of what the inspector is able to see and is not all inclusive, see inspection agreement for more details on limitations.

Home Resource Solutions Page 6 of 27

2: EXTERIOR

Information

Inspection Method

Exterior Doors: Exterior Entry

Visual

Door

Steel

Siding, Flashing & Trim: Siding Material

Vinyl

Walkways, Patios & Driveways:

Driveway Material

Concrete

Siding, Flashing & Trim: Siding

StyleChannel

Decks, Balconies, Porches &

Steps: AppurtenanceDeck, Patio, Front Porch

Decks, Balconies, Porches & Steps: Material

Wood, Concrete

Some post on front porch have wood rot, this could lead to support failure, recommend repair.



Deficiencies

2.1.1 Siding, Flashing & Trim

CRACKING-MINOR



Siding showed cracking in one or more places. This is a result of temperature changes, and typical as homes with stucco age. Recommend monitoring.

Home Resource Solutions Page 7 of 27



2.1.2 Siding, Flashing & Trim

PAINT OVERSPRAY



Paint overspray on siding has discolored siding in some areas Recommendation
Contact a qualified professional.



2.2.1 Exterior Doors

HARDWARE DAMAGED



One or more pieces of door hardware are damaged. Recommend repair or replace.


2.3.1 Walkways, Patios & Driveways

DRIVEWAY CRACKING - MINOR



Minor cosmetic cracks observed, which may indicate movement in the soil. Recommend monitor and/or have concrete contractor patch/seal.

Home Resource Solutions Page 8 of 27



2.4.1 Decks, Balconies, Porches & Steps



DECK - WATER SEALANT REQUIRED

Deck is showing signs of weathering and/or water damage. Recommend water sealant/weatherproofing be applied.

Here is a helpful article on staining & sealing your deck.



2.4.2 Decks, Balconies, Porches & Steps

IMPROPER DECK CONSTRUCTION PRACTICES



Deck was observed to have general poor construction. Recommend qualified deck contractor evaluate.

Home Resource Solutions Page 9 of 27



2.5.1 Eaves, Soffits & Fascia

PAINT/FINISH FAILING



The paint or finish is failing. This can lead to deterioration and rot of the material. Recommend that the araes be properly prepared and painted / finished.



2.5.2 Eaves, Soffits & Fascia

WASPS NEST



Wasp nests were visible under the soffits. Recommend a qualified exterminator evaluate and remove.

Home Resource Solutions Page 10 of 27



Home Resource Solutions Page 11 of 27

3: ROOF

Information

Inspection Method

Roof

Roof Type/Style Gable




Coverings: MaterialAsphalt

Roof Drainage Systems: Gutter Material Aluminum Flashings: Material Aluminum

Deficiencies

3.1.1 Coverings

MOSS BUILDUP



Recommendation

Contact a qualified professional.





Home Resource Solutions Page 12 of 27

3.2.1 Roof Drainage Systems

DEBRIS



Debris has accumulated in the gutters. Recommend cleaning to facilitate water flow.

Here is a DIY resource for cleaning your gutters.

3.2.2 Roof Drainage Systems

GUTTER IMPROPERLY SLOPED




Gutter are improperly sloped in areas, which could result in runoff drainage around the foundation and possible structural shifting. Recommend qualified roofing or gutters contractor repair.

3.2.3 Roof Drainage Systems



GUTTER LEAKAGE

Gutters were observed to be leaking in one or more areas. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor evaluate and repair gutters to proper functionality.



3.4.1 Skylights, Chimneys & Other Roof Penetrations




WOOD ROT AROUND CHIMNEY CHASE

Wood rot is present around chimney chase, this can lead to deterioration and moisture intrusion, recommend repair.

Recommendation

Contact a qualified professional.



Home Resource Solutions Page 13 of 27

4: GARAGE

Information

Garage Door: MaterialMetal, Insulated

Garage Door: Type

Roll-Up

Deficiencies

4.1.1 Ceiling

DAMAGED



Garage ceiling was damaged. Recommend qualified contractor evaluate and repair to prevent moisture intrusion.

4.2.1 Floor

STAINING



Garage floor shows visible staining from oil/grease. Recommend scrubbing with a degreaser or cleaning solution.

Here is a DIY resource to help.

4.3.1 Walls & Firewalls

DAMAGED DRYWALL



Garage wall had damaged drywall. Recommend drywall contractor repair.

4.4.1 Garage Door

PANEL DAMAGE



Garage door panel is damaged and may need repair/replacement. Recommend a qualified garage door contractor evaluate.



Home Resource Solutions Page 14 of 27

Home Resource Solutions Page 15 of 27

5: DOORS, WINDOWS & INTERIOR

Information

Windows: Window Manufacturer Windows: Window Type

Unknown

Walls: Wall Material

Drywall

Windows: Window Type Sliders, Casement

Ceilings: Ceiling Material

Gypsum Board

Floors: Floor Coverings Laminate, Tile, Carpet

Countertops & Cabinets:

CabinetryWood

Countertops & Cabinets: Countertop Material

Laminate

Deficiencies

5.1.1 Doors

SCREENDOOR TORN

Screendoor torn, recommend replacement

Recommendation

Contact a qualified professional.





5.3.1 Floors

CARPET STAINS



Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company

5.3.2 Floors

TILES LOOSE



Loose tiles are present at time of inspection. Recommend a qualified contractor re-attach and seal.

Home Resource Solutions Page 16 of 27

5.4.1 Walls

NAIL POPS



Protruding nail heads visible at the time of the inspection appeared to be the result of contact with moisture. After the source of moisture is located and corrected, protruding nails should be removed, drywall re-fastened and the drywall finished to match the existing wall surfaces. All work should be performed by a qualified drywall or painting contractor.

5.4.2 Walls



PAINT CRACKING

Wall paint was cracking in one or more areas. Recommend a qualified painter evaluate and apply a new coat.

Here is a DIY article on treating cracking paint.

5.4.3 Walls

POOR PATCHING

Sub-standard drywall patching observed at time of inspection. Recommend re-patching.

5.5.1 Ceilings

POSSIBLE MOLD



There are possible signs of fungi growth on ceiling. It is unknown if this is a safety hazard. Recommend a qualified mold inspector evaluate.



5.5.2 Ceilings

SAGGING DRYWALL



Ceiling drywall sagged visibly at the time of the inspection. This appears to be due to leakage from above. The source of moisture intrusion should be identified and corrected, and the damaged section of drywall replaced.

Home Resource Solutions Page 17 of 27




5.6.1 Steps, Stairways & Railings



BALUSTER SPACES TOO WIDE

The baluster space is not up to modern safety standards. The space between balusters should not allow passage of a 4 3/8-inch sphere for child safety. Recommend a qualified handyman or original installer repair and bring up to code.



Home Resource Solutions Page 18 of 27

6: PLUMBING

Information

Filters Water Source Main Water Shut-off Device:

Sediment Filter Public Location

Bathroom wall

Drain, Waste, & Vent Systems: Drain, Waste, & Vent Systems: Water Supply, Distribution

Drain Size Systems & Fixtures: Distribution

2" ABS **Material** Copper, PVC

Water Supply, Distribution Hot Water Systems, Controls,
Systems & Fixtures: Water Supply Flues & Vents: Capacity Flues & Vents: Location

Material 50 gallons Garage

Copper 50 gallons Garage

Hot Water Systems, Controls, Fuel Storage & Distribution Sump Pump: Location Flues & Vents: Power Systems: Main Gas Shut-off None

Flues & Vents: Power
Source/Type
Gas
Gas
Systems: Main Gas Shut-off
Location
Gas Meter

Hot Water Systems, Controls, Flues & Vents: Manufacturer

Rheem

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.



Deficiencies

Home Resource Solutions Page 19 of 27

6.2.1 Drain, Waste, & Vent Systems

IMPROPER CONNECTION



An improper connection was observed at a drain, waste or vent pipe. Recommend a qualified plumber evaluate and repair.

6.2.2 Drain, Waste, & Vent Systems



LEAKING PIPE

A drain, waste and/or vent pipe showed signs of a leak. Recommend a qualified plumber evaluate and repair.


6.3.1 Water Supply, Distribution Systems & Fixtures



DISTRIBUTION PIPE LEAKING

Distribution pipe was leaking. Recommend a qualified plumber evaluate and repair.





Home Resource Solutions Page 20 of 27

7: ELECTRICAL

Information

Service Entrance Conductors: Electrical Service Conductors Below Ground, 220 Volts Main & Subpanels, Service & Grounding, Main Overcurrent Device: Main Panel Location
Garage



Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Capacity
200 AMP

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Manufacturer Unknown

Branch Wiring Circuits, Breakers & Fuses: Branch Wire 15 and 20 AMP

Copper

Main & Subpanels, Service & Grounding, Main Overcurrent

Device: Panel Type

Circuit Breaker

Branch Wiring Circuits, Breakers & Fuses: Wiring Method Romex Main & Subpanels, Service & Grounding, Main Overcurrent Device: Sub Panel Location Exterior

Deficiencies

7.6.1 Smoke Detectors

LOW BATTERY

Smoke detector failed to respond when tested. Recommend battery be replaced.



Home Resource Solutions Page 21 of 27

8: ATTIC, INSULATION & VENTILATION

Information

Dryer Power Source

220 Electric

Attic Insulation: Insulation Type

Blown, Cellulose

Dryer VentMetal (Flex)

Attic Insulation: R-value

21

Flooring Insulation

Batt, Faced, Fiberglass

Ventilation: Ventilation Type

Gable Vents, Soffit Vents, Roof

vents

Exhaust Systems: Exhaust Fans

Fan Only

Deficiencies

8.1.1 Attic Insulation





Some insulation is compressed and displaced, it is recommended to even out and fill gaps for adequate protection from energy loss.

Recommendation

Contact a qualified professional.

Home Resource Solutions Page 22 of 27

9: FIREPLACE

Information

Type

Wood

Deficiencies

9.1.1 Vents, Flues & Chimneys



CHIMNEY LINER DIRTY

Chimney liner had layer of creosote dust, so underlying structure couldn't be inspected for cracks. Recommend qualified chimney sweep company inspect and/or clean.

Home Resource Solutions Page 23 of 27

10: HEATING

Information

Equipment: Brand

York

Equipment: Energy SourceGas

Equipment: Heat Type

Forced Air



Distribution Systems: Ductwork

Insulated

AFUE Rating

90

AFUE (Annual fuel utilization efficiency) is a metric used to measure furnace efficiency in converting fuel to energy. A higher AFUE rating means greater energy efficiency. 90% or higher meets the Department of Energy's Energy Star program standard.

Deficiencies

10.1.1 Equipment

FILTER DIRTY

The furnace filter is dirty and needs to be replaced every 6 months.



10.3.1 Distribution Systems

DUCT DAMAGED

Air supply duct was damaged. Recommend a qualified HVAC contractor repair.



Home Resource Solutions Page 24 of 27

11: COOLING

Information

Cooling Equipment: BrandYork

Model Number
VHE24B21SA

Serial Number
W168948454

Pactor Outdoor Use Only
Pour usage critical environment
(Charge state)

Pactor Outdoor Use Only
Pour usage critical environment
(Charge state)

Person on conception

Person on conception

Design Pressure
(Presson de conception)

Design Fresture
(Presson de conception)

Serial 1188

Confign Fresture
(North Confign Frest Vertical Confign F

Cooling Equipment: Energy Source/Type Heat Pump **Cooling Equipment: Location**Exterior North

Data plate

Distribution System:

Configuration

Central

Cooling Equipment: SEER Rating

3.4 SEER

Modern standards call for at least 13 SEER rating for new install.

Read more on energy efficient air conditioning at Energy.gov.

Home Resource Solutions Page 25 of 27

12: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

Information

Inspection Method

Visual

Foundation: Material

Concrete

Floor Structure:

Basement/Crawlspace Floor

Wood

Floor Structure: Material

Wood Beams

Floor Structure: Sub-floor

OSB

Deficiencies

12.1.1 Foundation

FOUNDATION CRACKS - MINOR



Minor cracking was noted at the foundation. This is common as concrete ages and shrinkage surface cracks are normal. Recommend monitoring for more serious shifting/displacement.

Here is an informational article on foundation cracks.

12.2.1 Basements & Crawlspaces

EFFLORESCENCE



Efflorescence noted on the crawlspace surface. This a white, powdery deposit that is consistent with moisture intrusion. This can compromise the soil's ability to support the home structure and/or lead to mold growth. Recommend a qualified contractor identify source or moisture and correct.

12.2.2 Basements & Crawlspaces

HIGH MOISTURE LEVELS



High levels of moisture were noted in areas of the basement. Recommend monitoring and finding source of moisture intrusion to prevent damage to structure.

12.3.1 Floor Structure

EVIDENCE OF WATER INTRUSION



There were signs of water intrusion in the underlying floor structure. Recommend identifying source of moisture and repairing.

12.4.1 Wall Structure

CRACKS - MINOR



Home Resource Solutions Page 26 of 27

Minor cracking was observed in wall structure. This is common in homes this age. Recommend monitoring.

Home Resource Solutions Page 27 of 27