
REPAIR REQUEST LIST

6358 Desert Peak Dr 03/28/2024 10:36 am

3.3.1 - Exterior: Site & Other Observations RODENT TRAPS OBSERVED



Rodent traps were observed around the exterior of the home. We recommend asking the seller is rodent activity has been observed in the past.

Several Areas Throughout






3.4.1 - Exterior: Grading & Drainage
GRADING AND DRAINAGE IS NEGATIVE OR NEUTRAL



Grading and drainage is either negative or neutral adjacent to the residence and moisture intrusion will remain a possibility. The soil or the hard surfaces should slope away from the residence to a distance of at least six feet to keep moisture away from the footings. We can elaborate on this issue, but you should seek a second opinion from a geologist or grading and drainage contractor.

Front




3.5.1 - Exterior: Exterior Siding Notes SEAL PENETATIONS/GAPS




Gaps and/or holes were observed on one or more sides in the siding around plumbing, gas, cable, wiring and/or other penetrations. We recommend sealing. Location Several Areas Throughout















3.5.2 - Exterior: Exterior Siding Notes MOISTURE STAINS




There are visible moisture stains under the eaves at the roof to wall transition near the gutters. Recommend correctionas necessary.

Location

Rear & Front







3.7.1 - Exterior: Fascia, Trim & Eaves
WEATHERED FASCIA AND TRIM
Cosmetic - Monitor - Maintenance

Sections of the fascia and trim are worn or weathered. Recommend maintenance.

Location Left Side & Front














3.9.1 - Exterior: Downspouts SPLASH BLOCKS MISSING

Cosmetic - Monitor - Maintenance

Some downspouts terminated close to, or against the home in one or more locations. We recommend splash blocks, or some other downspout extension, in these areas to ensure water runoff away from the structure.

Location

Several Areas Throughout





A door is missing its deadbolt plate and it should be replaced.

Location Rear from Garage



5.12.1 - Garage(s): Outlets, Electrical Observations REVERSE POLARITY




An outlet has reversed polarity. Recommend Repair.

To learn more why this is dangerous CLICK HERE



5.12.2 - Garage(s): Outlets, Electrical Observations COVERPLATE MISSING/DAMAGED



Coverplates were missing on outlets, switches or junction boxes. Recommend installing cover plates.



12.4.1 - Kitchen: Countertop MISSING OR DETERIORATED CAULK/GROUT



The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps sealed.



14.2.1 - Bathrooms: Trap and Drain

SLOW DRAIN



The sink drains slowly. Recommend repair.

Location

Master Bathroom & Powder Bathroom





14.4.1 - Bathrooms: Tub-Shower SHOWER-HEAD SPRAYS EVERYWHERE



The shower head is occluded by minerals, and does not spray uniformly.


2nd Floor Left Side Bathroom



14.4.2 - Bathrooms: Tub-Shower MISSING OR DETERIORATED CAULK/GROUT



The tub surround has missing or deteriorated caulk/grout. Recommend caulking or sealing.





14.6.1 - Bathrooms: Countertop MISSING OR DETERIORATED CAULK/GROUT



The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps filled to prevent possible water intrusion.

Location

Basement Bathroom






One more doors have hardware that is missing or in need repair or adjustment.

Location

Basement Game Room



16.3.1 - Interior: Flooring CARPET IS STAINED



The carpet is stained. Recommend a thorough cleaning or replacement as needed.

Location

Left Front Basement Bedroom

