REPAIR REQUEST LIST

4055 S 2000 W 05/11/2024 8:17 am

3.2.1 - Exterior: Driveway, Walkways & Patio

MISSING RAIL



The stairs are missing graspable rails. These are recommended on stairs where (4) or more risers are present. Recommend repair.

Location

Front



3.4.1 - Exterior: Grading & Drainage
GRADING AND DRAINAGE IS NEGATIVE OR NEUTRAL



Grading and drainage is either negative or neutral adjacent to the residence and moisture intrusion will remain a possibility. The soil or the hard surfaces should slope away from the residence to a distance of at least six feet to keep moisture away from the footings. We can elaborate on this issue, but you should seek a second opinion from a geologist or grading and drainage contractor.

Right Side & Front








3.5.1 - Exterior: Exterior Siding Notes
VEGETATION IS ENCROACHING
Cosmetic - Monitor - Maintenance

Vegetation is encroaching on the structure. We recommend they be trimmed and kept back at a minimum of twelve inches away the walls and foundation.

Location

Several Areas Throughout



3.5.2 - Exterior: Exterior Siding Notes
DAMAGED VINYL SIDING - MINOR
Cosmetic - Monitor - Maintenance

 $Portions\ of\ the\ vinyl\ siding\ are\ missing,\ cracked\ or\ otherwise\ damaged.\ Recommend\ repair.$

Location


Several Areas Throughout







3.5.3 - Exterior: Exterior Siding Notes SEAL PENETATIONS/GAPS



Gaps and/or holes were observed on one or more sides in the siding around plumbing, gas, cable, wiring and/or other penetrations. We recommend sealing. Location

Several Areas Throughout



3.7.1 - Exterior: Fascia, Trim & Eaves TRIM MISSING/DAMAGED



Repair - Replace - Not Working

 $\ensuremath{\mathsf{A}}$ piece of trim is damaged or missing. Recommend repairs.


Location

Rear





3.9.1 - Exterior: Downspouts SPLASH BLOCKS MISSING



Some downspouts terminated close to, or against the home in one or more locations. We recommend splash blocks, or some other downspout extension, in these areas to ensure water runoff away from the structure.

Location Front & Rear





3.10.1 - Exterior: Exterior Doors MISSING DEADBOLT PLATE



A door is missing its deadbolt plate and it should be replaced.

Location

Left Side



3.10.2 - Exterior: Exterior Doors WEATHERED DOOR



One or more of the exterior doors was weathered. We recommend maintenance and minor repairs as needed.

Location Left Side



3.16.1 - Exterior: Deck
WEATHERED DECK



Portions of the deck were weathered and in need of minor repairs and maintenance.









3.16.2 - Exterior: Deck



A graspable handrail was not installed on the deck stairs. These are recommended when there are four steps. Recommend installing.



4.2.1 - Roof: Composition Shingle Roof Notes DAMAGED SHINGLES - MINOR

Cosmetic - Monitor - Maintenance

There were one or more shingles with minor damage. Recommend monitoring and repair as needed.









4.2.2 - Roof: Composition Shingle Roof Notes EXPOSED NAILS VISIBLE



There are one or more exposed nails. We recommend sealing all exposed nails.

Please visit our Trusted Resources page for a list of contractors who can assist with this.







5.3.1 - Garage(s): Garage Door & Hardware GARAGE DOOR COSMETIC DAMAGE Cosmetic - Monitor - Maintenance

The main garage door is functional, but has cosmetic damage. Recommend repair as needed.







5.5.1 - Garage(s): Slab Floor NO HAND RAIL



The stairs are missing graspable rails. These are recommended on stairs where (4) or more risers are present. We recommend rail be installed.



5.9.1 - Garage(s): Walls and Ceiling TYPICAL SETTLEMENT CRACKING ON WALLS AND CEILINGS



Observed typical settlement type cracking on walls and ceilings. Recommend monitoring.







11.1.1 - Water Heater & Plumbing: Water Heating System SEISMIC STRAPS - MISSING/INSUFFICIENT



The hot water heater was missing seismic straps or was insufficiently anchored. Recommend two straps to properly secure water heater in the case of an

Please visit our Trusted Resources page for a list of contractors who can assist with this.




11.1.2 - Water Heater & Plumbing: Water Heating System PIPES-CORROSION



There was corrosion observed on one or more of the supplypipes at the time of the inspection. This could indicate a past or present leak, recommend evaluation and repair by a qualified licensed professional.

Location

Basement



12.4.1 - Kitchen: Countertop
MISSING OR DETERIORATED CAULK/GROUT



The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps sealed.



12.5.1 - Kitchen: Exhaust Fan Notes NO EXTERIOR EXHAUST FOR GAS STOVE

 $The \ Kitchen \ has \ gas \ appliances, \ but \ there \ was \ no \ exhaust \ venting \ to \ the \ Exterior. \ We \ recommend \ improving \ ventilation.$



14.4.1 - Bathrooms: Tub-Shower
CAULKING OR SEALING
Cosmetic - Monitor - Maintenance

Gaps or opensings are observed around shower valves and fauct. Recommend sealing.

Location Hallway Bathroom



14.4.2 - Bathrooms: Tub-Shower MISSING OR DETERIORATED CAULK/GROUT



The tub surround has missing or deteriorated caulk/grout. Recommend caulking or sealing.

Location

Hallway Bathroom



14.5.1 - Bathrooms: Toilet


FUNCTIONAL BUT LOOSE



The toilet is functional, but loose on the floor and should be secured by a qualified technician for safety reasons, and to prevent possible damage or leaking from around the toilet.

Please visit our Trusted Resources page for a list of contractors who can assist with this.

Hallway Bathroom & Master Bathroom





16.3.1 - Interior: Windows BROKEN SEALS



One or more windows have broken hermetic seals. This is evident from fogging, or condensation forming between the panes of glass. This is cosmetic in nature. Recommend repair as desired.

Location Family Room



16.3.2 - Interior: Windows A <u>WINDOW LOCK IS MISSING OR DOES NOT ENGAGE</u>



A window lock is missing or does not engage. Recommended repair.







16.3.3 - Interior: Windows SCREENS DAMAGED/MISSING



Window screens were missing or damaged in one or more areas. Recommend installing.

Right Front Basement Bedroom & Basement Bathroom & Basement Family Room







16.3.4 - Interior: Windows

MOISTURE STAINING AT WINDOW



There is visible moisture staining at a window. There is no current moisture detected. Recommend continuous monitoring for any further moisture intrusion and correct as necessary.

Left Rear Basement Bedroom



16.13.1 - Interior: Outlets, Electrical MISSING / DAMAGED COVERS

Cosmetic - Monitor - Maintenance

There were missing / damaged covers that should be installed Location
Basement Hallway Closet

