	4 1 Omt mop			
Insured/Applicant Name: Billings Home Inspe	ections	Application	n / Policy #:	
Address Inspected: 2753 Vista Parkway , West Palm Beach, FL 33411				
Actual Year Built: 1956	1956 Date Inspected: 01/20/2019			
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ ☑ Main electrical service panel with interior doo ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re A Florida-	or label	,		
			obtained from the Florida licensed professional of e of the suitability, fitness or longevity of any of the	
Electrical System Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lice	ensed electrician.	
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 80  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, d * If single strand (aluminum branch) wiring, prov Connections repair via COPALUM crimp Connections repair via AlumniConn			tion of all work must be provided.	
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring ☑ Other (explain) Pointed screws		
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information	•			
Main Panel	Second Panel		Wiring Type	
Panel age: Approx 5 )	Panel age: Approx 20		☑ Copper ☐ NM, BX or Conduit	
Year last undated: Unknown	Year last undated. Unknown		LINIVI, BA OI COITUUIL	

Brand/Model: General Electric

Brand/Model: General Electric

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate <b>primary</b> heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?	]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No					
Supplemental Information					
Age of system: 13					
Year last updated: 2006					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☐ Yes ☑ No					
Is there any indication of an active leak? $\square$ Yes $\square$ No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Garage					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☐ ☐	Toilets □ □				
Refrigerator	Sinks				
Washing Machine	Sump pump □ □ ☑  Main shut off valve □ □				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
Original to home	☑ Copper				
Completely re-piped	□ PVC/CPVC				
X Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)    ☑ PEX					
Water heater 2006,bathroom and kitchen updated					
☐ Other (specify)					

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )						
Predominant Roof  Covering material: Architectural shingle  Roof age (years): 3  Remaining useful life (years): 20  Date of last roofing permit: 09/06/2016  Date of last update: 09/06/2016  If updated (check one):		Secondary Roof Covering material: Modified Bitumen Roof age (years): 3 Remaining useful life (years): 13 Date of last roofing permit: 09/06/2016 Date of last update: 09/06/2016 If updated (check one):				
☑ Full Replacement		☑ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement 100		% of replacement 100				
Overall condition:		Overall condition:				
<b>☑</b> Satisfactory		☑ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?  (check all that apply and explain below)  □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage □ N/A ☑ Damage/deterioration  Any visible signs of leaks □ Yes ☑ No  Attic/underside of decking □ Yes ☑ No  Interior ceilings □ Yes ☑ No		Any visible signs of damage / deterioration?  (check all that apply and explain below)  □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks □ Yes ☑ No  Attic/underside of decking □ Yes ☑ No  Interior ceilings □ Yes ☑ No				
Additional Comments/Observations (use additional pages if needed):  Roof permit #16081328, tankless water heater TPR valve not required.  All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.  Home Inspector Inspector Signature  Hi8637 License Number  O7/15/2019 Date						
mspecioi signature	THE	FICEUSE MUHINEI	DαlE			
Billings Home Inspections Company Name	Home Inspector License Type	5616440279 Work Phone				

**Special Instructions:** This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

### **Exterior Photos**



## **Electrical System**

Panel Photos





#### Hazards



Pointed screws sub-panel

## **HVAC System**

**HVAC** Equipment











## **Plumbing System**

Water Heater








Under cabinet plumbing & drains



Exposed Valves



Roof

Photos of Each Slope



**Predominant Roof** 

Visible signs of damage / deterioration

Minor deterioration are the shingles at the front right appears to be from tree before it was trimmed

