Insured/Applicant Name:	Kevin Hurley	Application / Policy #:			
Address Inspected: 146 E	Euclid Blvd, Lantana, FL 33462				
Actual Year Built: 1954		Date Inspected: 03/22/2022			
Minimum Photo Requirements					
🗹 Dwelling: Each side 🗹 Roof: Each slope 🗹 Plumbing: Water heater, under cabinet plumbing/drains, exposed valves					
Main electrical service panel with interior door label					
Electrical box with par	nel off				
All hazards or deficiencies noted in this report					
	A Florida-licensed inspector must	complete, sign and date this form.			

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System				
Separate documentation of any aluminum wiring r	emediation must be provid	led and certified by a lice	ensed electrician.	
Main Panel		Second Panel	_	
Type: ☑ Circuit breaker □ Fuse Total Amps: 200		Type: Circuit breaker  Fuse		
Is amperage sufficient for current usage? Yes	🗌 No (explain)	Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes □No (explain)		
		ie amperage camerent i		
Indicate presence of any of the following:				
□ Cloth wiring				
☐ Active knob and tube				
$\Box$ Branch circuit aluminum wiring (If present, de	escribe the usage of all al	uminum wiring):		
* If single strand (aluminum branch) wiring, provi	de details of all remediation	on. Separate documenta	tion of all work must be provided.	
$\Box$ Connections repair via COPALUM crimp				
□ Connections repair via AlumniConn				
Hazards Present				
		Double taps		
Blowing fuses		Exposed wiring		
Empty sockets		Unsafe wiring		
Loose Wiring		□ Improper breaker size		
☐ Tripping breakers				
Improper grounding		□ Other (explain)		
□ Over fusing				
General condition of the electrical system: Satisfactory Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: Est 5 year:	Panel age: Est 5 year		Copper	
Year last updated: Est 2017	Year last updated: Est 2	017	NM, BX or Conduit	
Brand/Model: Square D	Brand/Model: Square D			

1-Stop Home Inspections 03/22/2022

#### **HVAC System**

Central heat: ☑ Yes □ No

If not central heat, indicate primary heat source and fuel type: \_\_\_\_

Are the heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🗌 No (explain)

Date of last HVAC servicing/inspection:

#### Hazards Present

Wood burning stove or central gas fireplace not professionally installed? 
See Yes No

Space heater used as primary heat source?  $\Box$  Yes  $\blacksquare$  No

Is the source portable? ☐ Yes ☑ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

Supplemental Information

Age of system: 2020, 2012

Year last updated:

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System								
Is there a temperature Is there any indication Is there any indication Water heater location	n of an active I n of a prior lea	eak? 🗆 Yes 🗹 No		]No				
General condition of	f the following	g plumbing fixture	es and connections	to applicances:				
Dishwasher Refrigerator Washing Machine Water Heater Showers/Tubs If unsatisfactory, ple	Satisfactory	Unsatisfactory	N/A	Toilets Sinks Sump pump Main shut off valve All other visible <b>ts, mold, corrosion, g</b>	Satisfactory		N/A	
Supplemental Inf	ormation							
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) Water supply lines updated est 2000			Type of pipes (chec ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)	k all that appl	( <u>(</u>			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Predominant Roof	Secondary Roof			
Covering material: Concrete Tile	Covering material: BUR			
Roof age (years): 15	Roof age (years): 14			
Remaining useful life (years): 10	Remaining useful life (years): 5			
Date of last roofing permit: 09/11/2007	Date of last roofing permit: 09/11/2007			
Date of last update:	Date of last update:			
If updated (check one):	If updated (check one):			
✓ Full Replacement	☑ Full Replacement			
Partial Replacement	Partial Replacement			
% of replacement	% of replacement			
Overall condition:	Overall condition:			
☑ Satisfactory	☑ Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
□ Cracking	□ Cracking			
Cupping/Curling	Cupping/Curling			
Excessive granule loss	Excessive granule loss			
$\Box$ Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
☐ Missing/loose/cracked tabs or tiles	$\Box$ Missing/loose/cracked tabs or tiles			
$\Box$ Soft spots in decking	□ Soft spots in decking			
□ Visible hail damage	□ Visible hail damage			
Any visible signs of leaks 🛛 Yes 🗹 No	Any visible signs of leaks 🛛 Yes 🗹 No			
Attic/underside of decking  Yes  No	Attic/underside of decking  Yes  No			
Interior ceilings 🗆 Yes 🗹 No	Interior ceilings 🗆 Yes 🗹 No			

Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be I certify that the above statements ar	1 0 ,	fiable Florida-licensed inspector.				
M West	Michael Tibbetts	HI11530	03/22/2022			
Inspector Signature	Title	License Number	Date			
1-Stop Home Inspections	Home Inspector	5614497541				
Company Name	License Type	Work Phone				

1-Stop Home Inspections 03/22/2022

**Special Instructions:**This sample4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# Photos, Additional Comments or Observations

**Exterior Photos** 





## **Electrical System**

Panel Photos























# HVAC System

## HVAC Equipment





#### **Plumbing System**

Water Heater



Under cabinet plumbing & drains







#### Exposed Valves





#### Roof

Photos of Each Slope



