Insured/Applicant Name:	John Doe		Applio	ication / Policy #:			
Address Inspected: 1234	sunny Florida , Tam	pa, FL 32066					
Actual Year Built: 2017			Date Inspected:	10/13/2023			
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report							
A Florida-licensed inspector must complete, sign and date this form.							
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.							
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.							
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			Second Panel  Type: □ Circuit breaker □ Fuse  Total Amps: □ Is amperage sufficient for current usage? □ Yes □ No (explain)				
Indicate presence of any	of the following:						
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumiConn							
Hazards Present  Blowing fuses Tripping breakers Empty sockets Corrosion Loose Wiring Improper grounding Over fusing			☑ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scoring ☐ Other (explain)				
General condition of the electrical system: ☐ Satisfactory ☑ Unsatisfactory (explain)  Double taps are present at main panel							
Supplemental inform							
Main Panel Second Panel				Wiring Type			
Panel age: 6 Year last undated: N/A		Panel age:		☑ Copper ☑ NM, BX or Conduit			

Brand/Model:

Brand/Model: Cutler Hammer

HVAC System						
Central AC: ✓ Yes ☐ No  Central heat: ✓ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type:						
Date of last HVAC servicing/inspection:						
Hazards Present  Wood burning stove or central gas fireplace <i>not professionally installed</i> ? ☐ Yes ☑ No  Space heater used as primary heat source? ☐ Yes ☑ No  Is the source portable? ☐ Yes ☑ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No						
Supplemental Information						
Age of system: 2017  Year last updated: N/A  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:  Garage manufacture date 2023						
General condition of the following plumbing fixtures and connections to applicances:						
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System:  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  ☐ Copper  ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)					

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)							
Predominant Roof Covering material: 3-Tab Roof age (years): 6 Remaining useful life (years): 9 Date of last roofing permit: 02/13/201 Date of last update: If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):					
☐ Full Replacement		☐ Full Replacement					
☐ Partial Replacement		□ Partial Replacement					
% of replacement		% of replacement					
Overall condition:		Overall condition:					
☐ Satisfactory		☐ Satisfactory					
☑ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)					
Any visible signs of damage / deterior (check all that apply and explain below)  Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes Attic/underside of decking Yes No	s No o	Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/Curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No					
Additional Comments/Observations (use additional pages if needed):  All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.							
	ue and correct.						
Brandon Keinhardt	Certified Professional Inspect	HI12840	10/13/2023				
Inspector Signature	Title	License Number	Date				
Bully Property Inspections LLC	State & Federal ID Numbers	727-859-7880					
Company Name	License Type	Work Phone	<del>_</del>				

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

#### **Exterior Photos**









## **Electrical System**

Panel Photos










Hazards



Double tar

## **HVAC System**

## **HVAC** Equipment







# **Plumbing System**

#### Water Heater








Under cabinet plumbing & drains



Exposed Valves



#### Photos of Each Slope



## **Predominant Roof**

#### Overall Condition



