

Florida Department of Agriculture and Consumer Services Division of Agricultural Environmental Services

WOOD-DESTROYING ORGANISMS INSPECTION REPORT

Section 482.226, F. S. and Rule 5E-14.142, F.A.C. Telephone Number (850) 617-7997

SECTION 1 – GENERAL INI	FORMATION
Inspection Company: SOUTHEASTERN TERMITE & PEST MANAGEMENT, INC. Inspection Company Name 1100 BARNETT DRIVE, SUITE 8 Company Address LAKE WORTH, FL 33461 Company City, State and Zip Code Inspector's Name and Identification Card Number: Address of Property Inspected: 313 8 Sw. Moldenglow DY Structure(s) on Property Inspected: 5 FH: Inspection and Report requested by: Brashield Home Name and Contact Informs SECTION 2 – INSPECTION FINDINGS – CONSUMERS SI THIS REPORT IS MADE ON THE BASIS OF WHAT WAS VISIBLE AND READILY ACCONSTITUTE A GUARANTEE OF THE ABSENCE OF WOOD-DESTROYING ORGAI	Business License Number: 561-540-1075 Date of Inspection: 9/17/9 ELA JE17193 PAIM CITY # 3499 Card No. Section of different from above HOULD READ THIS SECTION CAREFULLY CCESSIBLE AT THE TIME OF INSPECTION AND DOES NOT NISMS (WDOs) OR DAMAGE OR OTHER EVIDENCE UNLESS
THIS REPORT SPECIFICALLY STATES HEREIN THE EXTENT OF SUCH GUARANT This report does not cover areas such as, but not limited to, those that are enclosed or inaccessible, articles, insulation or any portion of the structure in which inspection would necessitate removing or This property was not inspected for any fungi other than wood-decaying fungi, and no opinion on her Individuals licensed to perform pest control are not required, authorized or licensed to inspect or reputealth or indoor air quality issues related to any fungi. Persons concerned about these issues should qualified to render such opinions. A wood-destroying organism (WDO) means an arthrop in a structure, namely, termites, powder post beetles, old house borers, and wood NOTE: This is NOT a structural damage report. it should be understood that there FURTHER INVESTIGATION BY QUALIFIED EXPERTS OF THE BUILDING TRADE S SOUNDNESS OF THE PROPERTY.	areas concealed by wall-coverings, floor coverings, furniture, equipment, stored defacing any part of the structure. alth related effects or indoor air quality is provided or rendered by this report. In the fact of any fungi other than wood-destroying fungi, nor to report or comment on do consult with a certified industrial hygienist or other person trained and condor plant life which damages and can reinfest seasoned wood addecaying fungi. In the damage, including possible hidden damage present. The structural services are the structural services and can reinfest seasoned wood and the damage present. The structural services are the structural services are the structural services and can reinfest seasoned wood and the structural services are the structural services and services are the structural services are the structural services are the structural services are the structural services and services are the structural services are the struct
Based on a visual inspection of accessible areas, the following fit (See Page 2, Section 3 to determine which areas of the inspected strum. A. Wo visible signs of WDO(s) (live, evidence or damage) observed. B. UVISIBLE evidence of WDO(s) was observed as follows:	
1. LIVE WDO(s): (Common Name of Organism and Location (Common Name of Organism and Location) (Common Name of Organism and Location)	n – use additional name if needed)
2. EVIDENCE of WDO(s) (dead wood-destroying insects or insect parts, (Common Name, Description and Location – Describe evic	
☐ 3. DAMAGE caused by WDO(s) was observed and noted as follows:	
(Common Name, Description and Location of all visible dar	mage — Describe damage use additional page, if needed)
CONTINUED ON PAG	E TWO

SECTION 3 - OBSTRUCTIONS AND INACCESSIBLE AREAS: The following areas of the structure(s) inspected were obstructed or inaccessible. NO INFORMATION on the status of wood-destroying organisms or damage from wood-destroying organisms in these areas is provided in this report. In addition to those areas described in consumer information on Page 1, Section 2; the following specific areas were not visible and/or accessible for inspection. The descriptions and reasons for inaccessibility are stated below: M Attic SPECIFIC AREAS: OF ATTIC REASON: INSULATION, INACCESSIBLE SPECIFIC AREAS: _____ ☐ Interior REASON: ☐ Exterior SPECIFIC AREAS: REASON: SPECIFIC AREAS: ☐ Crawlspace REASON: SPECIFIC AREAS: WALL VOIDS Other: REASON: INACCESSIBLE SECTION 4 - NOTICE OF INSPECTION AND TREATMENT INFORMATION EVIDENCE of previous treatment observed: Yes No If Yes, the structure exhibits evidence of previous treatment. List what was observed: _____ (State what visible evidence was observed to suggest possible previous treatment – use additional page, if needed) NOTE: The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment history and any warranty or service agreement which may be in place. A Notice of Inspection has been affixed to the structure at: ______ This Company has treated the structure(s) at the time of inspection ☐ Yes ☐ No If Yes: Common name of organism treated: (Common name of organism) Name of Pesticide Used: Terms and Conditions of Treatment: Method of treatment: ☐ Whole structure ☐ Spot treatment: Specify Treatment Notice Location: SECTION 5 - COMMENTS AND FINANCIAL DISCLOSURE Comments: (Use additional pages, if necessary) Neither the company (licensee) nor the inspector has any financial interest in the property inspected or is associated in any way in the transaction or with any party to the transaction other than for inspection purposes. Signature of Licensee or Agent/Robert/Hanaw Address of Property Inspected: 31385 w Holdinglow DV Inspection Date: